

# Oil Field Environmental Incident Summary

**Incident:** 20150629140106      **Date/Time of Notice:** 06/29/2015 14:01

**Responsible Party:** SECURE ENERGY SERVICES USA, LLC

**Well Operator:** SECURE ENERGY SERVICES USA, LLC

**Well Name:** WATFORD SWD 1

**Field Name:** PEMBROKE

**Well File #:** 90166

**Date Incident:** 6/28/2015      **Time Incident:** 17:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 149

**Rng:** 98

**Sec:** 6

**Qtr:**

**Location Description:**

**Submitted By:** Sean Hammersmark

**Received By:**

**Contact Person:** Sean Hammersmark  
555 17TH ST STE 800  
DENVER, CO 80202-3908

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine	30	Barrels
-------	----	---------

Other

**Description of Other Released Contaminant:**

Production water.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Minimal.

**Areal Extent:**

N/A

***Potential Environmental Impacts:***

None. Spill was caught and cleaned up immediately.

***Action Taken or Planned:***

None needed

***Wastes Disposal Location:*** Dirt was disposed of at 13 Mile landfill and water was disposed of onsite.

***Agencies Involved:***

***Updates***

---

***Date:*** 6/29/2015    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** O'Gorman, Brian

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to equipment failure, remained on location, within dike, according to the report. NDIC retains oversight.